

154




FIG. 2






FIG. 3



٧٥١



က
၁
၂
၃




FIG. 6







FIG. 7



G. 8



IG. 9



A perspective drawing of a rectangular plate with four small, square fasteners or bolts at the corners. The plate is shown from a slightly elevated angle, revealing its thickness. The fasteners are positioned at the corners of the top surface.

G. 10




FIG. 11




FIG. 12

